




AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT				1. CONTRACT ID CODE		PAGE OF PAGES 1 1									
2. AMENDMENT/MODIFICATION NO. P00001		3. EFFECTIVE DATE 02/06/91		4. REQUISITION/PURCHASE REQ. NO.		5. PROJECT NO. (If applicable) WOR# EP427-88									
6. ISSUED BY DIRECTORATE OF CONTRACTING BLDG. 465 DORMITORY ROAD P.O. BOX 140 FT. LEONARD WOOD, MO 65473-0140		CODE DABT31		7. ADMINISTERED BY (If other than item 6) DIRECTORATE OF CONTRACTING CONTRACT ADMINISTRATION DIV. P. O. BOX 140, (314) 596-7111 FT. LEONARD WOOD, MO. 65473-0140		CODE DOC-CA									
8. NAME AND ADDRESS OF CONTRACTOR (No., street, county, State and ZIP Code) HOF CONSTRUCTION COMPANY 3137 JAMIESON AVENUE ST. LOUIS MO 63139- Vendor ID 00006613				<div style="font-size: 2em; opacity: 0.5; transform: rotate(-45deg); position: absolute; top: 0; left: 0;">DUPLICATE ORIGINAL</div> <div style="text-align: center;">(X)</div>		9A. AMENDMENT OF SOLICITATION NO.									
						9B. DATED (SEE ITEM 11)									
						10A. MODIFICATION OF CONTRACT/ORDER NO. DABT31-90-C-0044									
CODE 0CF82 FACILITY CODE				X		10B. DATED (SEE ITEM 13) 09/13/90									
11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS															
<input type="checkbox"/> The above numbered solicitation is amended as set forth in item 14. The hour and date specified for receipt of Offers <input type="checkbox"/> is extended, <input type="checkbox"/> is not extended. Offers must acknowledge receipt of this amendment prior to the hour and date specified in the solicitation or as amended, by one of the following methods: (a) By completing items 8 and 15, and returning _____ copies of the amendment; (b) By acknowledging receipt of this amendment on each copy of the offer submitted; or (c) By separate letter or telegram which includes a reference to the solicitation and amendment numbers. FAILURE OF YOUR ACKNOWLEDGMENT TO BE RECEIVED AT THE PLACE DESIGNATED FOR THE RECEIPT OF OFFERS PRIOR TO THE HOUR AND DATE SPECIFIED MAY RESULT IN REJECTION OF YOUR OFFER. If by virtue of this amendment you desire to change an offer already submitted, such change may be made by telegram or letter, provided each telegram or letter makes reference to the solicitation and this amendment, and is received prior to the opening hour and date specified.															
12. ACCOUNTING AND APPROPRIATION DATA (If required) 21020800000762090515294.K2000256 NO CHANGE															
13. THIS ITEM APPLIES ONLY TO MODIFICATIONS OF CONTRACTS/ORDERS, IT MODIFIES THE CONTRACT/ORDER NO. AS DESCRIBED IN ITEM 14.															
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width: 5%; text-align: center;">(X)</td> <td style="width: 95%;">A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT ORDER NO. IN ITEM 10A.</td> </tr> <tr> <td></td> <td>B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation date, etc.) SET FORTH IN ITEM 14, PURSUANT TO THE AUTHORITY OF FAR 43.103 (b).</td> </tr> <tr> <td style="text-align: center;">X</td> <td>C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF: FAR 43.103 (a)(3)</td> </tr> <tr> <td></td> <td>D. OTHER (Specify type of modification and authority)</td> </tr> </table>								(X)	A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT ORDER NO. IN ITEM 10A.		B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation date, etc.) SET FORTH IN ITEM 14, PURSUANT TO THE AUTHORITY OF FAR 43.103 (b).	X	C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF: FAR 43.103 (a)(3)		D. OTHER (Specify type of modification and authority)
(X)	A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT ORDER NO. IN ITEM 10A.														
	B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation date, etc.) SET FORTH IN ITEM 14, PURSUANT TO THE AUTHORITY OF FAR 43.103 (b).														
X	C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF: FAR 43.103 (a)(3)														
	D. OTHER (Specify type of modification and authority)														
						30098843  220 Superfund									
E. IMPORTANT: Contractor <input type="checkbox"/> is not, <input checked="" type="checkbox"/> is required to sign this document and return <u>2</u> copies to the issuing office.															
14. DESCRIPTION OF AMENDMENT/MODIFICATION (Organized by UCF section headings, including solicitation/contract subject matter where feasible.) THE ABOVE CITED CONTRACT WITH HOF CONSTRUCTION COMPANY TO RENOVATE THREE WAREHOUSES AT ST. LOUIS, MO. IS HEREBY MODIFIED AS FOLLOWS: 1. The contract completion date is extended by thirty three (33) calendar days to 16 march 1991. 2. All other terms and conditions of the contract remain unchanged.															
Except as provided herein, all terms and conditions of the document referenced in item 8A or 10A, as heretofore changed, remains unchanged and in full force and effect.															
15A. NAME AND TITLE OF SIGNER (Type or print) Daniel A Hof, President				15A. NAME AND TITLE OF CONTRACTING OFFICER (Type or print) Paulette Bloch											
15B. CONTRACTOR/OFFEROR  (Signature of person authorized to sign)		15C. DATE SIGNED 2-12-91		15B. UNITED STATES OF AMERICA  (Signature of Contracting Officer)		15C. DATE SIGNED 19 Feb 91									

MAXVIN

AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT

1. CONTRACT ID CODE

PAGE OF PAGES

1 1

2. AMENDMENT/MODIFICATION NO.

p00002

3. EFFECTIVE DATE

03/13/91

4. REQUISITION/PURCHASE REQ. NO.

5. PROJECT NO. (if applicable)

WORS EP427-88

6. ISSUED BY

CODE

DOC-CA

7. ADMINISTERED BY (if other than item 6)

CODE

DIRECTORATE OF CONTRACTING
CONTRACT ADMINISTRATION DIV.
P. O. BOX 140, (314) 596-7111
FT. LEONARD WOOD, MO. 65473-0140

DUPLICATE ORIGINAL

8. NAME AND ADDRESS OF CONTRACTOR (No., street, county, State and ZIP Code)

HOF CONSTRUCTION COMPANY

3137 JAMIESON AVENUE
ST. LOUIS

MO 63139-

Vendor ID 00006613

9A. AMENDMENT OF SOLICITATION NO.

9B. DATED (SEE ITEM 11)

10A. MODIFICATION OF CONTRACT/ORDER NO.

DABT31-90-C-0044

10B. DATED (SEE ITEM 13)

09/13/90

CODE

OCF82

FACILITY CODE

11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS

☐ The above numbered solicitation is amended as set forth in item 14. The hour and date specified for receipt of Offers ☐ is extended, ☐ is not extended. Offers must acknowledge receipt of this amendment prior to the hour and date specified in the solicitation or as amended, by one of the following methods: (a) By completing items 8 and 15, and returning _____ copies of the amendment; (b) By acknowledging receipt of this amendment on each copy of the offer submitted; or (c) By separate letter or telegram which includes a reference to the solicitation and amendment numbers. FAILURE OF YOUR ACKNOWLEDGMENT TO BE RECEIVED AT THE PLACE DESIGNATED FOR THE RECEIPT OF OFFERS PRIOR TO THE HOUR AND DATE SPECIFIED MAY RESULT IN REJECTION OF YOUR OFFER. If by virtue of this amendment you desire to change an offer already submitted, such change may be made by telegram or letter, provided each telegram or letter makes reference to the solicitation and this amendment, and is received prior to the opening hour and date specified.

12. ACCOUNTING AND APPROPRIATION DATA (if required)

210208000000762090515294.K2000256 NO CHANGE

13. THIS ITEM APPLIES ONLY TO MODIFICATIONS OF CONTRACTS/ORDERS, IT MODIFIES THE CONTRACT/ORDER NO. AS DESCRIBED IN ITEM 14.

(X) A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT ORDER NO. IN ITEM 10A.

B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation date, etc.) SET FORTH IN ITEM 14, PURSUANT TO THE AUTHORITY OF FAR 43.103 (b).

X C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF:
FAR 43.103 (a)(3)

D. OTHER (Specify type of modification and authority)

E. IMPORTANT: Contractor ☐ is not, ☒ is required to sign this document and return 2 copies to the issuing office.

14. DESCRIPTION OF AMENDMENT/MODIFICATION (Organized by UCF section headings, including solicitation/contract subject matter where feasible.)

THE ABOVE CITED CONTRACT WITH HOF CONSTRUCTION COMPANY TO RENOVATE THREE WAREHOUSES AT ST. LOUIS, MO. IS HEREBY MODIFIED AS FOLLOWS:

1. The contract completion date is extended by fourteen (14) calendar days to 30 march 1991.

2. All other terms and conditions of the contract remain unchanged.

Except as provided herein, all terms and conditions of the document referenced in item 9A or 10A, as heretofore changed, remains unchanged and in full force and effect.

15A. NAME AND TITLE OF SIGNER (Type or print)

Daniel A Hof, President

16A. NAME AND TITLE OF CONTRACTING OFFICER (Type or print)

Paulette Bloch

15B. CONTRACTOR/OFFEROR

Daniel Hof
(Signature of person authorized to sign)

15C. DATE SIGNED

3-18-91

16B. UNITED STATES OF AMERICA

BY *Paulette Bloch*
(Signature of Contracting Officer)

16C. DATE SIGNED

03/25/91



Est. 1911

April 11, 1991

3137 JAMIESON AVE.
ST. LOUIS, MO. 63139

TEL: (314) 645-2200
FAX: (314) 645-2653

Bob Lick.

U.S. Army Reserve Center
Mr. Marvin Sack
4301 Goodfellow Blvd.
St. Louis, MO 63120

Re: Renovate Three Warehouses
Contract # DABT-31-C-0044

Dear Mr. Sack:

Following is the list of difficiencies discovered on our inspection of
April 11, 1991.

South Building:

1. Repair broken block at interior of east window, south wall
2. Rear door at south end, rust repair at bottom
3. Front door at north end, rust repair at bottom
4. Saw cut and seal crack on dock at new repair
5. Fix masonry where window meets sill, all locations

Middle Building:

1. Caulk/tuckpoint lintels as necessary (exterior)
2. Fix masonry where window meets sill, all locations

North Building:

1. Caulk/tuckpoint crack on south wall under and east of east window
2. Caulk/tuckpoint lintels as necessary (exterior)
3. Remove abandoned electric wire behind building
4. Saw cut and seal crack on dock at new repair
5. Fix masonry where window meets sill, all locations


Submitted by,

HOF CONSTRUCTION, INC.


A handwritten signature in cursive script that reads "Daniel Hof".


Daniel A. Hof
President

mb




PLOT PLAN





PLOT PLAN



LABEL	LOCATION	DRAWING #	MATERIAL DESCRIPTION	RESULTS
A	CENTER FLOOR	BLDG. # 219 B.	RED ON WHITE	
B	" "	BLDG. # 219 C.	" "	
C	" "	BLDG. # 219 E	" "	
D	" "	BLDG. # 219 F	" "	
E	" "	BLDG. # 219 H	" "	
F	" "	BLDG. # 219 J	" "	
G	" "	BLDG. # 219 A	" "	
H	" "	BLDG. # 219 A.	" "	
I	CENTER ROOM CEILING	BLDG. # 219 A	WOOL APPEARANCE.	
J	CENTER FLOOR	BLDG. # 219 D	RED ON WHITE.	
K	" "	BLDG. # 219 D.	" "	
L	" "	BLDG. # 219 D	" "	
M	EAST ROOM CEILING	BLDG. # 219 D	WOOL APPEARANCE.	
N	CENTER FLOOR	BLDG. # 219 G	RED ON WHITE	
O	" "	BLDG. # 219 G	" "	
P	" "	BLDG. # 219 G	" "	
Q	WEST ROOM CEILING	BLDG. # 219 G	WOOL APPEARANCE.	
R	1/2 OF SAMPLE "G"	BLDG. # 219 A	RED ON WHITE	
S	1/2 OF SAMPLE "L"	BLDG. # 219 D	" "	
T	← OPEN →			
U	SE SIDE	BLDG. # 219 A	PIPE FITTING.	
V	NE SIDE	BLDG. # 219 A	PIPE COVERING.	
W	NW CORNER	BLDG. # 219 A	PIPE COVERING & FITTING.	
X	SW SIDE	BLDG. # 219 A.	PIPE COVERING	
Y	NW SIDE @ TUNNEL	BLDG. # 219 D	PIPE COVERING	
Z	NE CORNER	BLDG. # 219 D	PIPE FITTING.	
AA	E SIDE	BLDG. # 219 D	PIPE COVERING.	
BB	SE CORNER	BLDG. # 219 D	PIPE FITTING & COVERING.	
CC	ESIDE N END.	BLDG. # 219 G	PIPE COVERING.	
DD	NSIDE W END	BLDG. # 219 G	PIPE COVERING.	
EE	WSIDE N END.	BLDG. # 219 G	PIPE COVERING.	
FF	NE CORNER	BLDG. # 219 G	PIPE FITTING.	
GG	1/2 OF SAMPLE "W"	BLDG. # 219 A		
HH	1/2 OF SAMPLE "A-A"	BLDG. # 219 D		
II	1/2 OF SAMPLE "C-C"	BLDG. # 219 G		
JJ	PANEL BOX.	BLDG. # 219 D	WIRE COVERING	

ECOSAFE

INCORPORATED

ECOSAFE INDUSTRIAL HYGIENE LABORATORY

BULK SAMPLE ANALYSIS

Client: U.S. Army Reserve Center
4301 Goodfellow Blvd, Rm. 181
St. Louis, MO 63123

EcoSafe Job No.: 89-616

Date Received: 10/20/89

Purchase Order No.: 2051

Date Reported: 10/20/89

Lab No.	Sample No.	Asbestos Detected & Percentage *	Fibrous Material & Percentage	Non-Fibrous Material % and Appearance
9878	4085-A	Chrysotile 15-30		Gypsum 15-30, quartz 15-30, unidentified other 5-15 - Red
9879	4085-B	Chrysotile 15-30	Cellulose <1	Quartz 15-30, unidentified other 30-50 - Red
9880	4085-C	Chrysotile 5-15		Gypsum 5-15, quartz 15-30, unidentified other 30-50 - Red
9881	4085-D	Chrysotile 5-15		Gypsum 1-5, quartz 15-30, unidentified other 30-50 - Red
9882	4085-E	Chrysotile 5-15		Gypsum 5-15, quartz 15-30, unidentified other 30-50 - Red
9883	4085-F	Chrysotile 15-30		Gypsum 15-30, quartz 5-15, unidentified other 15-30 - Red

Comments:

- * The upper detection limit is 100 percent.
The lower detection limit is less than 1 percent.

EcoSafe, Inc. is Accredited by the American Industrial Hygiene Association Accreditation Number 334 and also accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program for Bulk Asbestos Analysis using Polarized Light Microscopy with Dispersion Staining.

ECOSAFE INDUSTRIAL HYGIENE LABORATORY

BULK SAMPLE ANALYSIS

Client: U.S. Army Reserve Center EcoSafe Job No.: 89-616
 4301 Goodfellow Blvd, Rm. 181
 St. Louis, MO 63120 Date Received: 10/20/89

Purchase Order No.: 2051 Date Reported: 10/20/89

Lab No.	Sample No.	Asbestos Detected & Percentage *	Fibrous Material & Percentage	Non-Fibrous Material % and Appearance
9884	4085-G	Chrysotile 15-30		Gypsum 15-30, quartz 5-15, unidentified other 15-30 - Red
9885	4085-H	Chrysotile 15-30		Gypsum 15-30, quartz 5-15, unidentified other 15-30 - Red
9886	4085-I	Chrysotile <1	Cellulose 1-5, mineral wool >75, woolastonite 1-5	Gray
9887	4085-J	Chrysotile 5-15		Gypsum 5-15, quartz 15-30, unidentified other 30-50 - Red
9888	4085-K	Chrysotile 5-15		Gypsum 1-5, quartz 15-30, unidentified other 30-50 - Red
9889	4085-L	Chrysotile 5-15		Gypsum 1-5, quartz 15-30, unidentified other 30-50 - Red

Comments: _____

- * The upper detection limit is 100 percent.
 The lower detection limit is less than 1 percent.

EcoSafe, Inc. is Accredited by the American Industrial Hygiene Association Accreditation Number 334 and also accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program for Bulk Asbestos Analysis using Polarized Light Microscopy with Dispersion Staining.

ECOSAFE INDUSTRIAL HYGIENE LABORATORY

BULK SAMPLE ANALYSIS

Client: U.S. Army Reserve Center EcoSafe Job No.: 89-616
 4301 Goodfellow Blvd, Rm. 181
 St. Louis, MO 63123 Date Received: 10/20/89


Purchase Order No.: 2051 Date Reported: 10/20/89

Lab No.	Sample No.	Asbestos Detected & Percentage *	Fibrous Material & Percentage	Non-Fibrous Material % and Appearance
9890	4085-M	None Detected	Mineral wool >75	Gray
9891	4085-N	Chrysotile 5-15		Gypsum 1-5, , quartz 15-30, unidentified other 30-50 - Red
9892	4085-O	Chrysotile 15-30		Gypsum 1-5, quartz 5-15, unidentified other 30-50 - Red

Comments:

- * The upper detection limit is 100 percent.
 The lower detection limit is less than 1 percent.

EcoSafe, Inc. is Accredited by the American Industrial Hygiene Association Accreditation Number 334 and also accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program for Bulk Asbestos Analysis using Polarized Light Microscopy with Dispersion Staining.


 Jane Wasilewski
 Laboratory Superintendent

ECOSAFE

INCORPORATED

ECOSAFE INDUSTRIAL HYGIENE LABORATORY

BULK SAMPLE ANALYSIS

Client: U.S. Army Reserve Center EcoSafe Job No.: 89-616
4301 Goodfellow Blvd, Rm. 181
St. Louis, MO 63123 Date Received: 10/20/89

Purchase Order No.: 2051 Date Reported: 10/20/89

Lab No.	Sample No.	Asbestos Detected & Percentage *	Fibrous Material & Percentage	Non-Fibrous Material % and Appearance
9893	4085-P	Chrysotile 5-15	Cellulose 1-5	Gypsum 30-50, quartz 30-50, unidentified other 1-5 - Red/white
9894	4085-Q	None Detected	Cellulose 1-5, mineral wool >75	Unidentified other 1-5 - Green
9895	4085-R	Chrysotile 5-15	Cellulose 1-5	Gypsum 15-30, quartz 30-50, unidentified other 15-30 - Red
9896	4085-S	Chrysotile 5-15	Cellulose <1	Gypsum 30-50, quartz 30-50, unidentified other 5-15 - Red

Comments: _____

- * The upper detection limit is 100 percent.
The lower detection limit is less than 1 percent.

EcoSafe, Inc. is Accredited by the American Industrial Hygiene Association Accreditation Number 334 and also accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program for Bulk Asbestos Analysis using Polarized Light Microscopy with Dispersion Staining.


Phillip Hooper
Assoc. Industrial Hygienist

ECOSAFE

INCORPORATED

ECOSAFE INDUSTRIAL HYGIENE LABORATORY

BULK SAMPLE ANALYSIS

Client: U.S. Army Reserve Center EcoSafe Job No.: 89-624
4301 Goodfellow Blvd, Rm. 181
St. Louis, MO 63120 Date Received: 10/24/89

Purchase Order No.: 2064 Date Reported: 10/24/89

Lab No.	Sample No.	Asbestos Detected & Percentage *	Fibrous Material & Percentage	Non-Fibrous Material & Appearance
9939	AA	Amosite 15-30, Chrysotile 30-50	Cellulose 1-5	Gypsum 5-15, paint <1 - Pink
9940	BB	Amosite 15-30, Chrysotile 15-30	Cellulose 5-15	Gypsum 15-30 - Pink
9941	CC	Amosite 15-30, Chrysotile 15-30		Gypsum 30-50 - White
9942	DD	Amosite 15-30, Chrysotile 30-50	Cellulose 1-5	Gypsum 5-15 - White
9943	EE	Amosite 30-50, Chrysotile 15-30	Cellulose <1	Gypsum 15-30 - White
9944	FF	Chrysotile >75	Cellulose 1-5	Unidentified other 1-5 - Brown
9945	GG	Amosite 15-30, Chrysotile 15-30	Cellulose 5-15	Gypsum 15-30 - White
9946	HH	Amosite 30-50, Chrysotile 15-30		Gypsum 15-30, paint <1 - White

Comments:

- * The upper detection limit is 100 percent.
The lower detection limit is less than 1 percent.

EcoSafe, Inc. is Accredited by the American Industrial Hygiene Association Accreditation Number 334 and also accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program for Bulk Asbestos Analysis using Polarized Light Microscopy with Dispersion Staining.

ECOSAFE INDUSTRIAL HYGIENE LABORATORY

BULK SAMPLE ANALYSIS

Client: U.S. Army Reserve Center EcoSafe Job No.: 89-624
4301 Goodfellow Blvd, Rm. 181
St. Louis, MO 63120 Date Received: 10/24/89


Purchase Order No.: 2064 Date Reported: 10/24/89

Lab No.	Sample No.	Asbestos Detected & Percentage *	Fibrous Material & Percentage	Non-Fibrous Material % and Appearance
9947	II	Amosite 15-30, Chrysotile 15-30	Cellulose 5-15	Gypsum 15-30 - White
9948	U	Amosite 5-15, Chrysotile 30-50	Cellulose 5-15	Gypsum 15-30, paint <1 - Pink
9949	V	Amosite 15-30, Chrysotile 15-30	Cellulose 1-5	Gypsum 15-30, unidentified other
9950	W	Amosite 15-30, Chrysotile 30-50		Gypsum 15-30 - White
9951	X	Amosite 15-30, Chrysotile 15-30	Cellulose 5-15	Gypsum 15-30 - White
9952	Y	Amosite 15-30, Chrysotile 15-30	Cellulose 1-5	Gypsum 30-50 - White
9953	Z	Amosite 5-15, Chrysotile 30-50	Cellulose 1-5, mineral wool 1-5	Gypsum 15-30 - White

Comments:

- * The upper detection limit is 100 percent.
The lower detection limit is less than 1 percent.

EcoSafe, Inc. is Accredited by the American Industrial Hygiene Association Accreditation Number 334 and also accredited by the National Institute of Standards and Technology, National Voluntary Laboratory Accreditation Program for Bulk Asbestos Analysis using Polarized Light Microscopy with Dispersion Staining.


Jane Wasilewski
Laboratory Superintendent